

US EPA RECORDS CENTER REGION 5



440681

**PHOTOGRAPH LOG  
FOR  
FORMULATED PRODUCTS SITE  
CLYDE, SANDUSKY COUNTY, OHIO  
TDD: T05-9410-073  
PAN: EOH1026FBA**

Prepared by: *Frank C. T. Smith*  
Reviewed by: *John W. Jones*  
Approved by: *Ann G. Ball*

Date: 10.13.94  
Date: 10/13/94  
Date: 10.13.94



**ecology and environment, inc.**

6777 ENGLE ROAD, CLEVELAND, OHIO 44130, TEL. (216) 243-3330  
International Specialists in the Environment



SITE NAME: **FORMULATED PRODUCTS** TDD: **T059410073** PAN: **EOH1026FBA**  
 DIRECTION: **EAST** DATE: **06/16/94** PHOTOGRAPHER: **FD**  
 DESCRIPTION: **VIEW OF THE WEST SIDE OF THE FACILITY. THE SUPPORT ZONE IS LOCATED TO THE LEFT.**



SITE NAME: **FORMULATED PRODUCTS** TDD: **T059410073** PAN: **EOH1026FBA**  
 DIRECTION: **EAST** DATE: **06/16/94** PHOTOGRAPHER: **FD**  
 DESCRIPTION: **THE HAZCAT TRAILER IS IN THE BACKGROUND. TO THE LEFT IS THE PERIMETER FENCING THAT SURROUNDED THREE SIDES OF THE SITE.**





SITE NAME: **FORMULATED PRODUCTS** TDD: **T059410073** PAN: **EOH1026FBA**  
 DIRECTION: **SOUTHWEST** DATE: **06/20/94** PHOTOGRAPHER: **SW**  
 DESCRIPTION: **BOTTLES FROM LAB AREA STAGED IN THE OFFICE AREA OF BUILDING 5.**



SITE NAME: **FORMULATED PRODUCTS** TDD: **T059410073** PAN: **EOH1026FBA**  
 DIRECTION: **SOUTHEAST** DATE: **06/20/94** PHOTOGRAPHER: **SW**  
 DESCRIPTION: **BOTTLES FROM LAB AREA STAGED AND SEPARATED INTO TENTATIVE GROUPS IN BUILDING 5.**





SITE NAME: FORMULATED PRODUCTS TDD: T059410073 PAN: EOH1026FBA  
 DIRECTION: WEST DATE: 06/20/94 PHOTOGRAPHER: SW  
 DESCRIPTION: PAINT CANS AND FLAMMABLE SOLIDS/LIQUIDS FOUND IN LAB AREA OF BUILDING 5.



SITE NAME: FORMULATED PRODUCTS TDD: T059410073 PAN: EOH1026FBA  
 DIRECTION: SOUTHEAST DATE: 06/20/94 PHOTOGRAPHER: SW  
 DESCRIPTION: MISCELLANEOUS CHEMICALS FOUND IN LAB AREA OF BUILDING 5.





SITE NAME: FORMULATED PRODUCTS TDD: T059410073 PAN: EOH1026FBA  
 DIRECTION: SOUTH DATE: 06/20/94 PHOTOGRAPHER: SW  
 DESCRIPTION: MISCELLANEOUS CHEMICALS STAGED IN LAB AREA OF BUILDING 5



SITE NAME: FORMULATED PRODUCTS TDD: T059410073 PAN: EOH1026FBA  
 DIRECTION: SOUTH DATE: 06/20/94 PHOTOGRAPHER: FD  
 DESCRIPTION: TAT LABELING CHEMICAL CONTAINERS FOUND IN LAB AREA. THE CONTAINERS IN THE FOREGROUND; FL-057, CHLORDANE DUST, AND BUZZAWAY WERE LAB PACKED.





SITE NAME: FORMULATED PRODUCTS TDD: T059410073 PAN: EOH1026FBA  
 DIRECTION: EAST DATE: 06/22/94 PHOTOGRAPHER: SW  
 DESCRIPTION: ERCS CREW MEMBER TAKING INVENTORY OF CAUSTIC  
 STOCKPILE LOCATED IN BUILDING 3.



SITE NAME: FORMULATED PRODUCTS TDD: T059410073 PAN: EOH1026FBA  
 DIRECTION: EAST DATE: 06/22/94 PHOTOGRAPHER: FD  
 DESCRIPTION: TAT MEMBER LABELING DRUMS IN BUILDING 3.





SITE NAME: **FORMULATED PRODUCTS** TDD: **T059410073** PAN: **EOH1026FBA**  
 DIRECTION: **NORTHEAST** DATE: **06/22/94** PHOTOGRAPHER: **SW**  
 DESCRIPTION: **ERCS CREW MEMBER REMOVING LIQUID DRUMS FROM TOP OF WHAT WAS THE CAUSTIC STOCKPILE IN BUILDING 3.**




SITE NAME: **FORMULATED PRODUCTS** TDD: **T059410073** PAN: **EOH1026FBA**  
 DIRECTION: **SOUTHEAST** DATE: **06/23/94** PHOTOGRAPHER: **FD**  
 DESCRIPTION: **DRUMS REMOVED FROM THE STOCKPILE IN BUILDING 3.**





SITE NAME: FORMULATED PRODUCTS TDD: T059410073 PAN: EOH1026FBA  
 DIRECTION: SOUTH DATE: 06/28/94 PHOTOGRAPHER: SW  
 DESCRIPTION: CONTAMINATED WOOD DEBRIS, METAL AND PLASTIC FROM THE  
 STOCKPILE IN BUILDING 3.



SITE NAME: FORMULATED PRODUCTS TDD: T059410073 PAN: EOH1026FBA  
 DIRECTION: NORTH DATE: 06/23/94 PHOTOGRAPHER: SW  
 DESCRIPTION: CAUSTIC SODA SEPARATED FROM THE STOCKPILE IN BUILDING  
 3.





SITE NAME: FORMULATED PRODUCTS TDD: T059410073 PAN: EOH1026FBA  
 DIRECTION: WEST DATE: 06/23/94 PHOTOGRAPHER: SW  
 DESCRIPTION: ROLL-OFF BOX 003. ONE OF THREE BOXES USED TO BULK  
 BASE SOLIDS. A PLATFORM WAS CONSTRUCTED TO HELP IN CUTTING OPEN  
 THE CAUSTIC SODA FILLED DRUMS.



SITE NAME: FORMULATED PRODUCTS TDD: T059410073 PAN: EOH1026FBA  
 DIRECTION: WEST DATE: 06/23/94 PHOTOGRAPHER: SW  
 DESCRIPTION: ERCS CREW BULKING BASE SOLID DRUMS IN BUILDING 3.



SITE NAME: FORMULATED PRODUCTS TDD: T059410073 PAN: EOH1026FBA  
 DIRECTION: WEST DATE: 06/27/94 PHOTOGRAPHER: SW  
 DESCRIPTION: ROLL-OFF BOX 005 WITH BASE SOLIDS STAGED IN BUILDING 3.



SITE NAME: FORMULATED PRODUCTS TDD: T059410073 PAN: EOH1026FBA  
 DIRECTION: WEST DATE: 06/28/94 PHOTOGRAPHER: SW  
 DESCRIPTION: ROLL-OFF BOX 006 WITH NEUTRAL SOLIDS STAGED IN BUILDING 3.





SITE NAME: **FORMULATED PRODUCTS** TDD: **T059410073** PAN: **EOH1026FBA**  
 DIRECTION: **WEST** DATE: **06/28/94** PHOTOGRAPHER: **SW**  
 DESCRIPTION: **ERCS CREW CLEANING UP CONTAMINATED DEBRIS IN BUILDING 3.**



SITE NAME: **FORMULATED PRODUCTS** TDD: **T059410073** PAN: **EOH1026FBA**  
 DIRECTION: **SOUTHEAST** DATE: **06/28/94** PHOTOGRAPHER: **SW**  
 DESCRIPTION: **THE BACKHOE WAS USED TO BREAK UP SOME OF THE NEUTRAL SOLID MATERIAL.**





SITE NAME: FORMULATED PRODUCTS TDD: T059410073 PAN: EOH1026FBA  
 DIRECTION: NORTHEAST DATE: 06/28/94 PHOTOGRAPHER: SW  
 DESCRIPTION: ERCS CREW MEMBERS ALSO USED A RECIPROCATING SAW TO CUT THE RUBBER-LIKE NEUTRAL SOLIDS.



SITE NAME: FORMULATED PRODUCTS TDD: T059410073 PAN: EOH1026FBA  
 DIRECTION: EAST DATE: 06/29/94 PHOTOGRAPHER: SW  
 DESCRIPTION: ERCS CREW MEMBERS USED THE RECIPROCATING SAW TO CUT UP THE CONTAMINATED WOOD PALLETS, AS REQUIRED BY MOST DISPOSAL FACILITIES.






SITE NAME: FORMULATED PRODUCTS TDD: T059410073 PAN: EOH1026FBA  
 DIRECTION: EAST DATE: 06/29/94 PHOTOGRAPHER: SW  
 DESCRIPTION: ROLL-OFF BOX 007 FILLED WITH CONTAMINATED PALLETS AND WOOD DEBRIS.



SITE NAME: FORMULATED PRODUCTS TDD: T059410073 PAN: EOH1026FBA  
 DIRECTION: SOUTH DATE: 06/30/94 PHOTOGRAPHER: FD  
 DESCRIPTION: ERCS CREW MEMBERS CONSOLIDATING THE ACID LIQUID WASTESTREAM.



SITE NAME: FORMULATED PRODUCTS TDD: T059410073 PAN: EOH1026FBA  
 DIRECTION: SOUTH DATE: 06/30/94 PHOTOGRAPHER: FD  
 DESCRIPTION: A DRUM OF CONSOLIDATED FLAMMABLE LIQUIDS. THE  
 RESPECTIVE DRUM AND CONTAINER NUMBERS OF CONSOLIDATED WASTES ARE  
 LISTED ON THE SIDE OF THE DRUM.



SITE NAME: FORMULATED PRODUCTS TDD: T059410073 PAN: EOH1026FBA  
 DIRECTION: EAST DATE: 06/30/94 PHOTOGRAPHER: SW  
 DESCRIPTION: ERCS CREW MEMBER CLEANING THE TOP OF A DRUM DURING  
 THE FLAMMABLE LIQUID CONSOLIDATION.





SITE NAME: FORMULATED PRODUCTS TDD: T059410073 PAN: EOH1026FBA  
 DIRECTION: SOUTH DATE: 06/30/94 PHOTOGRAPHER: SW  
 DESCRIPTION: DRUM OF FLAMMABLE LIQUIDS.



SITE NAME: FORMULATED PRODUCTS TDD: T059410073 PAN: EOH1026FBA  
 DIRECTION: NORTHEAST DATE: 06/30/94 PHOTOGRAPHER: SW  
 DESCRIPTION: ERCS CREW MEMBER CONSOLIDATING FLAMMABLE LIQUIDS IN  
 THE STAGING AREA LOCATED IN THE WEST END OF BUILDING 1.





SITE NAME: FORMULATED PRODUCTS TDD: T059410073 PAN: EOH1026FBA  
 DIRECTION: SOUTH DATE: 07/07/94 PHOTOGRAPHER: FD  
 DESCRIPTION: DRUM CONTAINING 4 PCB CAPACITORS. THE CAPACITORS  
 WERE DISPOSED OF AT GREAT LAKES ENVIRONMENTAL OF WARREN, MICHIGAN.



SITE NAME: FORMULATED PRODUCTS TDD: T059410073 PAN: EOH1026FBA  
 DIRECTION: WEST DATE: 07/07/94 PHOTOGRAPHER: FD  
 DESCRIPTION: 3000 GALLON VACUUM TRUCK USED TO EXTRACT THE NON-  
 HAZARDOUS SLUDGE FROM THE LARGE PIT AT THE EAST END OF THE FACILITY  
 LEAVES THE SITE.





SITE NAME: FORMULATED PRODUCTS TDD: T059410073 PAN: EOH1026FBA  
 DIRECTION: SOUTH DATE: 07/07/94 PHOTOGRAPHER: FD  
 DESCRIPTION: OVERPACK CONTAINING THE GLYCOL ETHER DRUM FOUND ON  
 SITE. THE DRUM WAS TRANSPORTED BY METROPOLITAN ENVIRONMENTAL TO  
 NORTH EAST CHEMICAL IN CLEVELAND, OHIO, FOR DISPOSAL.



SITE NAME: FORMULATED PRODUCTS TDD: T059410073 PAN: EOH1026FBA  
 DIRECTION: SOUTHWEST DATE: 07/08/94 PHOTOGRAPHER: FD  
 DESCRIPTION: PIT AT EAST END OF THE FACILITY AFTER BEING  
 ENCAPSULATED WITH CONCRETE. APPROXIMATELY 26.5 YD<sup>3</sup> WERE NEEDED TO  
 FILL THE PITS AND TRENCHES AT THE FACILITY.